

No Calibration Pen Type pH Tester AMT28

USER GUIDE

Quick Step for Use:

1. First time use or long time not use, turn off the meter and put sensor in the sample liquid or tap water (don't put sensor in distilled water) for about 2-5 minutes. Shake it gently in the water.
2. Long press ON/OFF button to start test, meter will display pH and temperature value alternately. Value will automatic hold when stable.
3. Short press ON/OFF, meter will test again.
4. Long press ON/OFF meter will shut off.
5. After 5 months or accuracy not good, meter in shut down state, long press about 15 seconds, till meter display "dEFA", release button and meter will reset to factory default.

Calibration (No need, this function only for professional user or meter work wrong!)

1. Though this meter no need calibration and easy to reset to factory default, it also can calibration by professional user.
2. Shut down meter, put sensor in the 6.86 buffer solution, shake it gently and wait for 2 minutes.
3. Long press ON/OFF about 10 seconds till meter display "CALI", meter will automatic calibration and no need any operation. After calibration finish, meter will turn off.

Maintenance:

1. Always clean the sensor after use by tap water.
2. Check the battery compartment to avoid water into or battery leakage.

AMTAST USA INC.

438 Skyline Dr. E Lakeland FL. 33809 USA

No Calibration Pen Type Surface pH Tester AMT28F

USER GUIDE

Quick Step for Use:

1. First time use or long time not use, turn off the meter and put sensor in the water liquid (don't put sensor in distilled water) for about 2-5 minutes. When test, spray some water first to the surface to make surface not too dry.
2. Long press ON/OFF button to start test, meter will display pH and temperature value alternately. Value will automatic hold when stable.
3. Short press ON/OFF, meter will test again.
4. Long press ON/OFF meter will shut off.
5. After 5 months or accuracy not good, meter in shut down state, long press about 15 seconds, till meter display "dEFA", release button and meter will reset to factory default.

Calibration (No need, this function only for professional user or meter work wrong!!)

1. Though this meter no need calibration and easy to reset to factory default, it also can calibration by professional user.
2. Shut down meter, put sensor in the 6.86 buffer solution, shake it gently and wait for 2 minutes.
3. Long press ON/OFF about 10 seconds till meter display "CALI", meter will automatic calibration and no need any operation. After calibration finish, meter will turn off.

Maintenance:

1. Always clean the sensor after use by tap water.
2. Check the battery compartment to avoid water into or battery leakage.

AMTAST USA INC.

438 Skyline Dr. E Lakeland FL. 33809 USA